

Firma \* Abteilung  
Strasse \* D-12345 Ort

**Demo11 GmbH  
Zentrallager  
Herr Demo11  
Wolfskaulstr. 84**

**D-66292 Riegelsberg**

Customer no **Z11**

Your order no **202508-2461**

Your order date **08/01/2025**

Ordered by **Herr Demo11**

Service date **08/07/2025**

Service technician **Volker**

Datum **08/12/2025**

### Service report V1 - UVV inspection - Bosch Rasenmäher

Hello Mr. Demo11,

We have carried out a service activity for you. The most important information is compiled into a service report. Thank you very much for your order!

Best regards




Volker, Technician

## Your inventory

Manufacturer	Bosch	Inventory no	Z01
Decsription	Rasenmäher	Your inventory no	2019-15
Type	Demo device		
Device number	SNR12345-67890	Next check	Aug 2026
Year	2019		
Location	in the garden		
Operating hours	250807		
Software version	1.0		
Hardware status	OK		
Modul information	minimum		

## X Badge assigned

We found a few small defects. There are no objections to its use. You will receive the new inspection sticker. However, marked defects should be eliminated promptly!



**Riegelsberg, 08/07/2025**

City, Date

Volker, Technician

Information on the service activity

Customer	Demo11 GmbH Zentrallager	Customer no	Z11
Manufacturer	Bosch	Inventory no	Z01
Description	Rasenmäher	Your inventory no	2019-15
Technician	Volker	Service date	08/07/2025 (30 min)
		Next check	Aug 2026

Pos	Checkpoint	Status
1	Electronic measurement Bem1	minor defects
2	Chains Verschleiß an den Ketten, wurden ausgetauscht	defects fixed
3	Driver seat and controls	✓
4	Electric equipment	✓
5	Frame, safety equipment	✓
6	Tires	✓
7	Exhaust gas	✓

## Spare parts

Pos	Name	Amount	Unity
1	Ausgebaut: kex1 Chains	2	Piece
	Installed: kex1 Chains	2	Piece
	Installation location: Drive unit		
	Error type: Wear		
	Implemented measure: Exchange		

## Accessory

Pos	Name	Amount	Unity
1	kela12 Chain bearing	2	Piece

## Disposable article

Pos	Name	Amount	Unity
1	Lubricant	0	Liter